



Warm Up Instructions for Trap Machines



(New In-line hydraulic heater)

(Timer)

1. Set Timer to 30 minutes
2. Wait 5 minutes
3. Only turn on pump
(pump switch)
4. After 30 minutes turn on machine



Note: This procedure is for initial start-up of trap machines when temperature is below 50 degrees